

**max
5kg**

2

3

4

A1 $\phi 8 \times 36$ x6

B11 7x50 x6

I1 $\phi 2$ x6








ZM1 x4

D20 6x9,5 x8


KR2 x4

G2 S-4 x1


NO	Dim			Col.-No	Qty
1	1200	200	16	1	1
2	1198	180	16	1	1
3	600	200	16	1	1
4	598	180	16	1	1




1











2










3









4






NO	Dim			Col.-No	Qty
1	298	400	16	1	1
2	298	400	16	1	1
3	298	380	16	1	1
4	298	380	16	1	1
5	1802	400	16	1	1
6	1802	400	16	1	1
10	589	309	3	1	2
11	600	309	3	1	1
8	596	326	16	1	2
7	596	161	25	1	2
14L	350	100	12	1	1
14P	350	100	12	1	1
13	551	86	16	1	2
12	561	353	3	1	2




(G4)		Ø 5	x4
(A1)		Ø 8x36	x32
(E1)		Kr0	x4
(B5)			x16
(D10)		3,5x13	x8
(B4)			x16
(E2)		H0	x4
(G5)		#15	x16
(EK2)		6,3x13	x8
(S1)			x14
(G1)			x1
(B3)			x10
(H6)		L-342mm	x4
(D9)		3x20	x4
(G16)			x4
(D8)		5x13	x8
(UW)		L-64	x2
(D18)		M4x9mm	x4
(UW1)		L-160	x2
(G2)		S-4	x1
(UP6)		4x30	x4
(UP16)		4x35	x4
(F12)			x6


1



2




3



E1
Kr0 x4

D10
3,5x13 x8

4



UP16
4x35 x4

UW1
L-160 x2

A1
Ø 8x36 x16

G1
x1

B3
x10

x2

x2

x2

x2

13

14P





12

7





x2

12











G3

5**6**

7









8






9













D18
M4x9mm x4





NO	Dim			Col.-No	Qty
1	954	330	16	1	1
2	954	330	16	1	1
5	568	310	16	1	1
12	567	295	6	1	1
3	602	330	16	1	1
4	602	330	16	1	1
6	965	579	3	1	1
9	596	326	16	1	1
7	596	652	16	1	1
11	422	366	4	1	1





A1 $\phi 8 \times 36$ x12

B5 x12

B4 x12

G5 #15 x12

G20 x4

LED x2

S1 x10

G4 $\phi 5$ x12

UW L-64 x2

P1 x4

UP6 4x30 x4

UP13 3x16 x4

F12 x4

E1 Kr0 x4

L1 x1

D10 3,5x13 x10

KR2 x1


E2 H0 x4

D22 4x40 x1


EK2 6,3x13 x8

G2 S-4 x1


1





2










3







4











5**6****7****7** $a=b$ 




8



9



10














D10
3,5x13
x2

L1
x1















KR2
x1

D22
4x40
x1





NO	Dim		Col.-No	Qty
1	954	330	16	1
2	954	330	16	1
4	568	310	16	1
11	567	295	6	1
3	602	330	16	1
5	965	579	3	1
8	596	326	16	1
6	596	652	16	1
10	422	366	4	1



A1 $\phi 8 \times 36$ x12

B5 x12

B4 x12

G5 #15 x12

G20 x4

S1 x10

UW L-64 x2

UP6 4x30 x4

ZR1 x2

G4 $\phi 5$ x12

P1 x4

UP13 3x16 x4

E1 Kr0 x4

D10 3,5x13 x8

D6 3,5x30 x4


KR2 x2

E2 H0 x4


EK2 6,3x13 x8

G2 S-4 x1


1




2










3




4



5**6****7** $a=b$ 

8




G5 #15 x12

ZR1 x2

D6 3,5x30 x4

G5





9



G4 Ø 5 x12



UW L-64 x2

UP6 4x30 x4



OŚWIETLENIE ZNAJDUJE SIĘ
W PACZCE SZAFKI
TYP 40

LED x1



10

